

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

April 4, 2002

Richard Dalton
HC 8C60 Box 1420
Bliss, Idaho 83314



LEE R. PETERSON
Watermaster

RECEIVED

APR 11 2002

Department of Water Resources
Southern Region

Dear Richard,

I recently checked all the diversions in the Gooding area and found that the Thorpe diversion # 0040 needs to have a weir installed and repairs to the headgate. Please have the necessary repairs done before you request delivery of the water. There will be no delivery of water to this diversion until the necessary repairs are complete. We have sent a copy of this letter to the other users on the system.

Idaho Code 42-701 states in part:
"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

CC: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451



LEE R. PETERSON
Watermaster

April 4, 2002

Howard Morris
1101 East 2900 South
Hagerman, Idaho 83332

Dear Mr. Morris,

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451



LEE R. PETERSON
Watermaster

April 4, 2002

Paul Zellar
1152 Old Malad River Hwy
Bliss, Idaho 83314

*Richard
Daulton*

Dear Paul,

I recently checked all the diversions in the Gooding area and found that the Thorpe diversion # 0040 needs to have a weir installed and repairs to the headgate. Please have the necessary repairs done before you request delivery of the water. There will be no delivery of water to this diversion until the necessary repairs are complete. We have sent a copy of this letter to the other users on the system.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451



LEE R. PETERSON
Watermaster

April 4, 2002

RECEIVED

Robert McCabe
5201 Wavecrest Way
Oxnard, CA 93035

COPY

APR 08 2002

Department of Water Resources
Southern Region

Dear Mr. McCabe,

I recently checked all the diversions in the Gooding area and found that the meter on your pump at Lower Frost #0039 needs to be repaired. Please have the necessary repairs done before you request delivery of the water. There will be no delivery of water to this diversion until the necessary repairs are complete. We have sent a copy of this letter to the other users on the system.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

CC: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451



LEE R. PETERSON
Watermaster

COPY

April 4, 2002

Paul Zellar
1152 Old Malad River Hwy
Bliss, Idaho 83314

RECEIVED

APR 08 2002

Department of Water Resources
Southern Region

Dear Paul,

I recently checked all the diversions in the Gooding area and found that the Thorpe diversion # 0040 needs to have a weir installed and repairs to the headgate. Please have the necessary repairs done before you request delivery of the water. There will be no delivery of water to this diversion until the necessary repairs are complete. We have sent a copy of this letter to the other users on the system.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

CC: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED
APR 08 2002
Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

April 4, 2002

COPY

Richard Dalton
HC 8C60 Box 1420
Bliss, Idaho 83314

Dear Richard,

I recently checked all the diversions in the Gooding area and found that the Thorpe diversion # 0040 needs to have a weir installed and repairs to the headgate. Please have the necessary repairs done before you request delivery of the water. There will be no delivery of water to this diversion until the necessary repairs are complete. We have sent a copy of this letter to the other users on the system.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".
Lee R. Peterson
Watermaster

CC: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451



LEE R. PETERSON
Watermaster

April 4, 2002

COPY

Howard Morris
1101 East 2900 South
Hagerman, Idaho 83332

RECEIVED
APR 08 2002
Department of Water Resources
Southern Region

Dear Mr. Morris,

I recently checked all the diversions in the Gooding area and found that the Thorpe diversion # 0040 needs to have a weir installed and repairs to the headgate. Please have the necessary repairs done before you request delivery of the water. There will be no delivery of water to this diversion until the necessary repairs are complete. We have sent a copy of this letter to the other users on the system.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

CC: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451



LEE R. PETERSON
Watermaster

April 4, 2002

COPY

RECEIVED
APR 08 2002
Department of Water Resources
Southern Region

David Morrow
Olympic Tower Apt 5a
1 manuel Rodriquez Serra
Condado, Puerto Rico Pu 009

Dear Mr. Morrow,

I recently checked all the diversions in the Gooding area and found that There is no meter on your pump 33-P. Please have the necessary repairs done before you request delivery of the water. There will be no delivery of water to this diversion until the necessary repairs are complete.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

CC: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

COPY



LEE R. PETERSON
Watermaster

April 4, 2002

Gary Osborne
1776 E 1625 S
Gooding, Idaho

RECEIVED

APR 08 2002

Department of Water Resources
Southern Region

Dear Gary,

I recently checked all the diversions in the Gooding area and found that There is no meter on your pump 35-P1, I already sent you a notice for repairs to 35-P3. Please have the necessary repairs done before you request delivery of the water. There will be no delivery of water to this diversion until the necessary repairs are complete.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

CC: IDWR